



# **VENDOR ASSESSMENT REPORT**

Vendor Assessment ID	VA-068695824231254
Name of the Vendor	FAST EARTHING ENTERPRISES
Address	FLAT NO 2,DHANKAWADI, PUNE,,DHANKAVDI,Pune,MAHARASHTRA,411043
Date of Report	14 Mar 2024
Date of Expiry	13 Mar 2027

#### **Contents:**

Section	Description
А	Desktop Assessment Details
В	Video Assessment Details
С	Final Remarks
D	Disclaimer

# Section-A Desktop Assessment

# (A-1) Vendor Profile:

Criteria	Parameters	Observations/Details
Company Details	Name of the Company/Firm	FAST EARTHING ENTERPRISES
	Registered Address	FLAT NO 2,DHANKAWADI, PUNE,,DHANKAVDI,Pune,MAHARASHTRA,411043
	Primary Contact Number	8600779121
	Primary Email ID	info.fastearthing@gmail.com
	Additional Contact Number	8600779121
	Additional Email ID	acc.fastearthing@gmail.com
	Constitution Type	firm
	Company Identification Number	Not Available
	GSTIN Number	27AAFFF5176M1ZY
	PAN/TAN/TIN of the Company	AAFFF5176M
	Company debarred/blacklisted by any Govt. organization (Yes/No)	No
Certificates & Licenses	Quality Certification (Yes/No)	Yes
	Any License (Yes/No)	Yes
Firm Category	OEM/Deemed OEM/Re-seller	OEM





Beneficiary Declaration	(Yes/No)	Yes
Transfer of Technology	(Yes/No)	No

### (A-2) Experience:

Details of Orders (Top Three Value- wise) received in last three financial years:

S.No.	Department Name	Work Order/ Completion Letter Number	Item Supplied	Quantity Supplied	Order Value (Rs.)
1	Purchase	UNIVASTU/WO/MEP/MUMBAI/METRO/2022- 23/17	GI STRIP	11500	₹45,01,770.00
2	PURCHASE	STE P L/ P O I MPT I 23'24 I O0LL9 Ame nd ed	Providing earthing arrangement by using I No. galvanizedcast iron earth plate ofsize 600 X 600 X I2m	94	₹6,43,336.00
3	Purchase				

#### (A-3) Turnover of the Vendor (Last 3 years)

S.No.	Assessment Year	Turnover (Rs)
1	2023	₹6,68,47,706.79

# (A-4) Items for which assessment is requested & carried out.

S. No	Category Name	Description	Remarks Valid/Invalid
1	Electrical Plug	Electrical Plugs As Per IS 1293(Q3)	invalid
2	Earth Electrode as per IS 3043	Earth Electrode as per IS 3043	valid
3	Earthing Powder	Earthing Powder	valid
4	Earthing Plate as per IS 3043	Earthing Plate as per IS 3043	valid
5	GI Grating ( in Number)	GI Grating ( In Number)	invalid
6	Wheel Set Earthing Equipment	Wheel Set Earthing Equipment(Q2)	invalid
7	Copper Rods And Bars For Electrical Purposes-IS:613	Copper Rods And Bars For Electrical Purposes-IS:613	valid

### (A-5) Desktop Assessment Remarks:





Vendor has submitted all the required documents and replied to the raised NCs with proper remarks along with the supporting documents.

# Section-B

(Applicable for OEM/Deemed OEM Only)

# (B-1) Vendor Capability:

Criteria	Parameters	Details
Basic Information	Number of production/service sites	1
Manufacturing Sites	Address of Manufacturing Site(s)	AT POST -KARANDI, TAL BHOR, DIST PUNE-412213
Country	Country of parent OEM (Applicable for Deemed OEM Only)	
Quality/ Process control	Availability of 'Quality Assurance Plan' document / 'Stage/component - Wise Inspection Plan' (Yes/No)	Yes
Safety	Availability of 'Safety Standard and operating procedures' manual (Yes/No)	Yes
Suppliers Component, Raw material	List of the approved suppliers along with quantity supplied (Yes/No)	No

# (B-2) Video Assessment:

Parameter	Information	Response (verified/not verified)
Seller's address	Whether the physical location of the vendor is as per address proof provided in desktop assessment.	Verified
Manufacturing process Flow details	Whether manufacturing process is as per 'process flow diagram provided' in desktop assessment.	Verified
Manufacturing process Equipment	Whether the machinery is available with vendor as per list provided in desktop assessment.	Verified
Infrastructure	Whether the vendor has sufficient resources like manpower, buildings etc. for its activities.	Verified

# **B-3: Photographs**










































































#### **Section-C**

#### Video Assessment Remarks (Applicable for OEM/Deemed OEM)

- 1. Video Assessment has been conducted with Sh.Balaji sopan kumbhar (partner) of the firm.
- 2. Video, pictorial evidence and geo-tagged location have been recorded successfully during video assessment.
- 3. Firm's address, manufacturing process, machine/equipment & infrastructure have been verified.
- 4. the Category "Electrical Plug, GI Grating & Wheel Set Earthing Equipment "found to be invalid due to non submission of required document as per the GeM Specification.
- 5. Video Assessment has been conducted successfully.

Recommendation- Based on the Vendor Assessment, Vendor has been assessed as an "OEM" satisfactorily only for the categories marked as "Valid".

#### Section-D

#### **Disclaimer**

- > This report is valid for 36 months from the date of report.
- $\,\succ\,\,$  This vendor assessment report is confidential and is addressed only to the intended recipient.
- > This information shall not be made available to third parties or any other person, entity or organization without the permission of the GeM or the verification agency.
- > The vendor assessment report is based on the information provided by the vendor on GeM Portal and to the verification agency portal which are considered to be truthful, precise and accurate.
- > GeM reserves the rights for any surveillance/Physical assessment of the vendor.
- > The responsibility for the accuracy, completeness or adequacy of any information on which report is based, lies with the vendor.
- > RITES accept no liability for the contents of this report or for the consequences of any actions taken on the basis of information provided in the report. Vendor Assessment is not an audit and this report is not in any way a recommendation for entering into any kind of transaction/commitment/agreement etc. with entity.
- > RITES accepts no responsibility, whatsoever, for any loss or damage from the use of any information given in the report and nothing contained in the report is liable or intended to create any legally binding obligations, financial or any other liability whatsoever on RITES, it's leadership or persons/organizations involved in vendor assessment.





\*\*\*End of Report\*\*\*